

General Environmental Incident Summary

Incident: 4158 **Date/Time Notice:** 7/5/2016 **DEM Incident No:**

Responsible Party: CHS

Date Incident: 7/5/2016 **Time Incident:** 1:54 pm **Duration:**

County: Ransom **Twp:** 134 **Rng:** 56 **Sec:** 11 **Qtr:**

Lat: 46.43287 **Long:** -97.68757 **Method:** Interpolation from map

Location Description: 411 Jackson Ave W, Lisbon, ND

Submitted By: Evan Fust

Affiliation:

Address: 5500 Cenex Dr

City: Inver Grove Heights

State: ND

Zip: 55077

Received By:

Contact Person:

5324 165th Ave SE
Kindred, ND

Distance Nearest Occupied Building:

Release Contained: No

Type of Incident: Tank Leak

Description of Released Contaminant: NH3

Volume Spilled: 30.00 gallons

Ag Related: Yes

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Yes

Cause of Incident:

Slight leak in valve

Risk Evaluation:

none

of Fatalities: 0

of Injuries: 0

Affected Medium: 01 - air

Potential Environmental Impacts:

none

Action Taken or Planned:

closed valve

Wastes Disposal Location: N/A

Agencies Involved:

Updates

Date: 7/5/2016 ***Status:*** Reviewed - No Action Required

Author: Crowdus, Kory

Updated Volume:

Notes:

Release into the air. Spoke with Division of Air Quality. No follow-up required for this release.